CLASSIFICATION

of office real estate

The classification is designed for the developing office real estate market of the Republic of Uzbekistan in accordance with international standards, and its main objective is to facilitate the development of this market.

The typology is carried out in 3 different classes (A, B, C) with division into subgroups. Belonging to a certain class implies compliance with the criteria described below. Our team has chosen the criteria that will encourage developers to improve the quality of their projects. At the same time, class A+ has been added. This class is fully in line with the best international quality standards, and it takes into account local climate.

Classes A+ and A are considered as a premium segment. They are aimed at large international companies and local institutional companies with their own standards of office fit-out. Classes B+ and B are suitable for medium sized companies who do not have strict corporate standards. Based on that, there can be a demand for any property, irrespective of its class.

This classification has been developed by CMWP | Uzbekistan for internal use in analytical work. It is also being made publicly available for consultants, appraisers, investors, and developers of the office real estate market in order to improve the quality of services in the commercial real estate market.

Class A+	Class A	Class B+	Class B			
BUILDING ENGINEERING SYSTEMS						
1.1 Heating, Ventilation, and Air Conditioning System (HVAC)						
HVAC which allows to regulate the temperature in the separate office block 24/7. Four-pipe system (Four-Pipe Heating/Cooling Fan Coil Unit with a Split Coil).	HVAC which allows to regulate the temperature in the separate office block 24/7.	Centralized HVAC.	HVAC.			
1.2 Fire security system						
With automatic detection, alert and fire-extinguishing systems.	With automatic detection, alert and fire-extinguishing systems.	With automatic detection, alert systems.	With automatic detection, alert systems.			
1.3 Elevators	1.3 Elevators					
Modern high-quality, high-speed elevators from leading international brands.	Modern high-quality, high-speed elevators from leading international brands.	Modern high-quality elevators for buildings with more than 3 storeys.	Modern high-quality elevators for buildings with more than 3 storeys.			
1.4 Elevator's maximum waiting time						
Not more than 30 seconds.	Not more than 60 seconds.	Recommendation: Not more than 60 seconds.	Recommendation: Not more than 60 seconds.			
1.5 Power supply	1.5 Power supply					
Two independent sources of electrical power supply or the availability of an uninterruptible power supply (power supply's capacity for tenant's low-voltage grids must be at least 50 W per 1 sqm of usable area + 20 W, additionally allocated for lighting).	Two independent sources of electrical power supply or the availability of an uninterruptible power supply (power supply's capacity for tenant's low-voltage grids must be at least 50 W per I sqm of usable area + 20 W, additionally allocated for lighting).	Recommendation: Two independent sources of electrical power supply or the availability of an uninterruptible power supply power supply (power supply's capacity for tenant's low-voltage grids must be at least 50 W per 1 sqm of usable area + 20 W, additionally allocated for lighting).	Recommendation: Two independent sources of electrical power supply or the availability of an uninterruptible power supply (power supply) (power supply's capacity for tenant's low-voltage grids must be at least 50 W per 1 sqm of usable area + 20 W, additionally allocated for lighting).			
1.6 Security system						
Modern security and access control systems in the building: CCTV for all the building's entries, perimeter, parking areas, as well as electronic pass system and round-the-clock security of the building.	Modern security and access control systems in the building: CCTV for all the building's entries, perimeter, parking areas, as well as electronic pass system and round-the-clock security of the building.	CCTV for all the building's entries and round-the-clock security of the building. Building's access control.	CCTV for all the building's entries and round-the-clock security of the building. Building's access control.			

Developer: Alexey Letunovsky Head of the Analytical Group CMWP | Uzbekistan

Version: 3.04 dated 22/03/2023 Approval: Denis Sokolov, FRICS CEO CMWP | Uzbekistan

Sokolov D.

Letunovsky A.

674



CLASSIFICATION

of office real estate

STRUCTURAL FEATURES OF THE BUILDING						
2.1 Ceiling height						
«slab-to-slab» – at least 3.5 meters.	«slab-to-slab» – at least 3.5 meters.	«clear height» – at least 2,7 meters.	«clear height» – at least 2,7 meters.			
2.2 Raised floor	2.2 Raised floor					
The building has been designed with the possibility to make a raised floor.	The building has been designed with the possibility to make a raised floor.	Recommendation: The building has been designed with the possibility to make a raised floor.				
2.3 Layout						
Open efficient floor layout. Construction with load-bearing columns. Columns should be spaced apart for not less than 6 x 6 meters.	Open efficient floor layout. Construction with load-bearing columns. Columns should be spaced apart for not less than 6 x 6 meters.	Open efficient layout of the whole or half leasable area of the building.	Recommendation: Open efficient layout of the whole or half leasable area of the building.			
2.4 Floor depth						
Floor depth should not be more than 20 m from window to window. Not more than 10 m from window to floor plate core and 12 m for buildings with non-regular forms and atriums.	Floor depth should not be more than 20 m from window to window. Not more than 10 m from window to floor plate core and 12 for buildings with non-regular forms and atriums.	Recommendation: Floor depth should not be more than 20 m from window to window. Not more than 10 m from window to floor plate core and 12 m for buildings with nonregular forms and atriums.				
2.5 Loss factor						
Loss factor should not exceed 12% per floor. Areas are measured according to the BOMA standards.	Loss factor should not exceed 20% per floor. Areas are taken from the buildings cadastre.	Recommendation: Loss factor should not exceed 20% per floor. Areas are taken from the buildings cadastre.	Recommendation: Loss factor should not exceed 20% per floor. Areas are taken from the buildings cadastre.			
2.6 Floor load capacity						
More than 400 kg/sqm.	More than 400 kg/sqm.	Recommendation: More than 400 kg/sqm.	Recommendation: More than 400 kg/sqm.			
2.7 Common area and f	2.7 Common area and facade finishing					
Usage of high-quality materials.	Usage of high-quality materials.	Usage of high-quality materials.	Recommendation: Usage of quality materials.			
2.8 Lighting and window	2.8 Lighting and window arrangement					
Modern, high-quality windows provide sufficient natural lighting. Triple-Glazed windows.	Modern, high-quality windows provide sufficient natural lighting. Double-Glazed windows.	Modern, high- quality windows provide sufficient natural lighting. Double-Glazed windows.	Recommendation: Modern, high- quality windows provide sufficient n atural lighting. Double-Glazed windows.			
LOCATION						
3.1 Location						
The property should be located in the area, where no other buildings or sites can pose a negative effect on its reputation (for example, functioning industrial sites, junkyards, etc.).	The property should be located in the area, where no other buildings or sites can pose a negative effect on its reputation (for example, functioning industrial sites, junkyards, etc.).	Recommendations: The property should be located in the area, where no other buildings or sites can pose a negative effect on its reputation (for example, functioning industrial sites, junkyards, etc.).				
3.2 Transport accessibility						
The building's location is not further than a 15-minute walk from the closest metro station or 5-minute walk from the closest public transport station.	The building's location is not further than a 15-minute walk from the closest metro station or 5-minute walk from the closest public transport station.	Recommendation: The building's location is not further than a 15-minute walk from the closest metro station or 5-minute walk from the closest public transport station.				

Developer: Alexey Letunovsky Head of the Analytical Group CMWP | Uzbekistan

Version: 3.04 dated 22/03/2023 Approval: Denis Sokolov, FRICS CEO CMWP | Uzbekistan

Sokolov D.

Letunovsky A.



CLASSIFICATION

of office real estate

Underground parking or covered multi-level above-ground parking. With level above-ground parking. At least one parking space for every los against the leasable area (parking ratio 1/000). WNERSHIP 5.1 Single or dual ownership The are two owners of the building at max (the building is not sold by separate blecks to different owners). BUILDING MANAGEMENT AND TENANT SERVICES 6.1 Building management Professional property management Professional property management Specialized property management Company. Specialized property management Specialized property management Specialized property management company. At least two quality TSP in the building in terms of its size. It should also provided an easy access to the office provided an easy access to the office provided parking. With least two quality TSP in the building in the standard parking space for every 100 sum of the leasable area (parking ratio 1/100). Becommendation: The are two owners of the building at max (the building in the standard parking space for every 100 sum of the leasable area (parking ratio 1/100). Becommendation: The are two owners of the building at max (the building in the standard parking space for every 100 sum of the leasable area (parking ratio 1/100). Becommendation: The are two owners of the building in the standard parking space for every 100 sum of the leasable area (parking ratio 1/100). Becommendation: The are two owners of the building in the standard parking space for every 100 sum of the leasable area (parking ratio 1/100). Becommendation: The are two owners of the building in the standard parking space for	PARKING						
### At least two quality TSP in the Duilding in rots appropriate for the Duilding in	4.1 Parking's description						
At least one parking space for every 30 sqm of the leasable area (parking atio /RO). OWNERSHIP 5.1 Single or dual ownership The are two owners of the building at max (the building is not sold by separate blocks to different owners). BUILDING MANAGEMENT AND TENANT SERVICES 6.1 Building management Professional property management Professional property management Professional property management Company. 6.2 Telecommunications Service Provider (TSP) At least two quality TSP in the building in the building in the sold states the building in terms of its size, it should also provide an easy access to the office zone. Well organized waiting area. 6.4 Amenities Caté/restaurant/dining room and other services in the building. 7.1 Certification according to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)	Underground parking or covered multi-level above-ground parking. Guest parking.	multi-level above-ground parking.	Organized guarded parking.				
100 sgm of the leasable area (parking pate for every 100 sgm of the leasable area (parking ratio 1/100). OWNERSHIP 5.1 Single or dual ownership The are two owners of the building at max (the building is not sold by separate blocks to different owners). BUILDING MANAGEMENT AND TENANT SERVICES 6.1 Building management Professional property management company. 6.2 Telecommunications Service Provider (TSP) At least two quality TSP in the building in the b	4.2 Parking ratio						
5.1 Single or dual ownership The are two owners of the building at max (the building is not sold by separate blocks to different owners). BUILDING MANAGEMENT AND TENANT SERVICES 6.1 Building management Professional property management Specialized property management Company. Specialized property management Specialized property management Company. At least two quality TSP in the building in the building in the building in the building. 6.3 Entrance Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. 6.4 Amenities Café/restaurant/dining room and other services in the building (ATM, shops, etc.) and in the vicinity of the surple, BREEAM or LEED) The are two owners of the building in the suilding in the pullding in the suilding in the services in the building (ATM, shops, etc.) and in the vicinity of the suilding of the services in the building (ATM, shops, etc.) and in the vicinity of the building in the services in the building (ATM, shops, etc.) and in the vicinity of the suildings to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)	At least one parking space for every 80 sqm of the leasable area (parking ratio 1/80).	100 sqm of the leasable area	parking space for every 100 sqm of the leasable area (parking ratio				
The are two owners of the building at max (the building at max (the building is not sold by separate blocks to different owners). BUILDING MANAGEMENT AND TENANT SERVICES 6.1 Building management Professional property management Specialized property management company. 6.2 Telecommunications Service Provider (TSP) At least two quality TSP in the building. At least two quality TSP in the building. Becommendation: Organized property management. 6.3 Entrance Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Café/restaurant/dining room and other services in the building (ATM, shops, etc.) and in the vicinity of the building of the solulding. CERTIFICATION 7.1 Certification according to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)	OWNERSHIP						
at max (the building is not sold by separate blocks to different owners). at max (the building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). building is not sold by separate blocks to different owners). Building is not sold by separate blocks to different owners). Creammendation: Organized property management orpanized property management operate property management. Creammendation: Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. building. Café/restaurant/dining room nearby. building. Café/restaurant/dining room nearby. c	5.1 Single or dual ownership						
Professional property management company. Specialized property management company. Organized property management property management company. 6.2 Telecommunications Service Provider (TSP) At least two quality TSP in the building. At least two quality TSP in the building the feet building. At least two quality TSP in the building in terms of the size. At least two quality TSP in the building. At least two quality TSP in the building in terms of the size. At least two quality TSP in the building in terms of the size. At least two quality TSP in the building in terms of the size. At least two quality TSP in the building in terms of the size in the building. At least two quality TSP in the buildi	The are two owners of the building at max (the building is not sold by separate blocks to different owners).	at max (the building is not sold by	owners of the building at max (the building is not sold by separate				
Professional property management company. Specialized property management company. Organized property management property management company. At least two quality TSP in the conditions. At least	BUILDING MANAGE	MENT AND TENANT	SERVICES				
company. compan	6.1 Building manageme	nt					
At least two quality TSP in the building. At least two quality TSP	Professional property management company.		Organized property management				
building. building. building. building. building. puilding. building. building. puilding. puilding. building. building. puilding. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized waiting area. Provide an easy access to the office zone. Well organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized receptio	6.2 Telecommunications Service Provider (TSP)						
Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Café/restaurant/dining room and other services in the building (ATM, shops, etc.) and in the vicinity of the building. CERTIFICATION CERTIFICATION 7.1 Certification according to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)	At least two quality TSP in the building.						
that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area. Organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area.	6.3 Entrance						
Café/restaurant/dining room and other services in the building (ATM, shops, etc.) and in the vicinity of the building. CERTIFICATION 7.1 Certification according to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)	Effectively organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well organized waiting area.	that is appropriate for the building in terms of its size. It should also provide an easy access to the office	organized reception zone that is appropriate for the building in terms of its size. It should also provide an easy access to the office zone. Well				
other services in the building (ATM, shops, etc.) and in the vicinity of the building. CERTIFICATION 7.1 Certification according to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)	6.4 Amenities						
7.1 Certification according to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)	Café/restaurant/dining room and other services in the building (ATM, shops, etc.) and in the vicinity of the building.	other services in the building (ATM,	Café/restaurant/dining room nearby.	Recommendation: Café/restaurant/dining room nearby.			
for buildings (for example, BREEAM or LEED)	CERTIFICATION						
Meets the standard Recommended Recommended Recommended	7.1 Certification according to one or more international environmental assessment methods for buildings (for example, BREEAM or LEED)						
	Meets the standard	Recommended	Recommended	Recommended			

Considering the current situation on the market, exclusion of one item, when the building undergoes the process of classification, is possible, due to the objective reasons.

Developer: Alexey Letunovsky Head of the Analytical Group CMWP | Uzbekistan

Version: 3.04 dated 22/03/2023 Approval: Denis Sokolov, FRICS CEO CMWP | Uzbekistan

Sokolov D.

Letun

Letunovsky A.

